

UNCLASSIFIED

FEB 81 P AGARWAL, P NATH, H J DOEBB

N62269-79-C-0283

NL

100  
200  
300  
400  
500  
600  
700  
800  
900  
1000  
1100  
1200  
1300  
1400  
1500  
1600  
1700  
1800  
1900  
2000  
2100  
2200  
2300  
2400  
2500  
2600  
2700  
2800  
2900  
3000  
3100  
3200  
3300  
3400  
3500  
3600  
3700  
3800  
3900  
4000  
4100  
4200  
4300  
4400  
4500  
4600  
4700  
4800  
4900  
5000  
5100  
5200  
5300  
5400  
5500  
5600  
5700  
5800  
5900  
6000  
6100  
6200  
6300  
6400  
6500  
6600  
6700  
6800  
6900  
7000  
7100  
7200  
7300  
7400  
7500  
7600  
7700  
7800  
7900  
8000  
8100  
8200  
8300  
8400  
8500  
8600  
8700  
8800  
8900  
9000  
9100  
9200  
9300  
9400  
9500  
9600  
9700  
9800  
9900  
10000  
10100  
10200  
10300  
10400  
10500  
10600  
10700  
10800  
10900  
11000  
11100  
11200  
11300  
11400  
11500  
11600  
11700  
11800  
11900  
12000  
12100  
12200  
12300  
12400  
12500  
12600  
12700  
12800  
12900  
13000  
13100  
13200  
13300  
13400  
13500  
13600  
13700  
13800  
13900  
14000  
14100  
14200  
14300  
14400  
14500  
14600  
14700  
14800  
14900  
15000  
15100  
15200  
15300  
15400  
15500  
15600  
15700  
15800  
15900  
16000  
16100  
16200  
16300  
16400  
16500  
16600  
16700  
16800  
16900  
17000  
17100  
17200  
17300  
17400  
17500  
17600  
17700  
17800  
17900  
18000  
18100  
18200  
18300  
18400  
18500  
18600  
18700  
18800  
18900  
19000  
19100  
19200  
19300  
19400  
19500  
19600  
19700  
19800  
19900  
20000  
20100  
20200  
20300  
20400  
20500  
20600  
20700  
20800  
20900  
21000  
21100  
21200  
21300  
21400  
21500  
21600  
21700  
21800  
21900  
22000  
22100  
22200  
22300  
22400  
22500  
22600  
22700  
22800  
22900  
23000  
23100  
23200  
23300  
23400  
23500  
23600  
23700  
23800  
23900  
24000  
24100  
24200  
24300  
24400  
24500  
24600  
24700  
24800  
24900  
25000  
25100  
25200  
25300  
25400  
25500  
25600  
25700  
25800  
25900  
26000  
26100  
26200  
26300  
26400  
26500  
26600  
26700  
26800  
26900  
27000  
27100  
27200  
27300  
27400  
27500  
27600  
27700  
27800  
27900  
28000  
28100  
28200  
28300  
28400  
28500  
28600  
28700  
28800  
28900  
29000  
29100  
29200  
29300  
29400  
29500  
29600  
29700  
29800  
29900  
30000  
30100  
30200  
30300  
30400  
30500  
30600  
30700  
30800  
30900  
31000  
31100  
31200  
31300  
31400  
31500  
31600  
31700  
31800  
31900  
32000  
32100  
32200  
32300  
32400  
32500  
32600  
32700  
32800  
32900  
33000  
33100  
33200  
33300  
33400  
33500  
33600  
33700  
33800  
33900  
34000  
34100  
34200  
34300  
34400  
34500  
34600  
34700  
34800  
34900  
35000  
35100  
35200  
35300  
35400  
35500  
35600  
35700  
35800  
35900  
36000  
36100  
36200  
36300  
36400  
36500  
36600  
36700  
36800  
36900  
37000  
37100  
37200  
37300  
37400  
37500  
37600  
37700  
37800  
37900  
38000  
38100  
38200  
38300  
38400  
38500  
38600  
38700  
38800  
38900  
39000  
39100  
39200  
39300  
39400  
39500  
39600  
39700  
39800  
39900  
40000  
40100  
40200  
40300  
40400  
40500  
40600  
40700  
40800  
40900  
41000  
41100  
41200  
41300  
41400  
41500  
41600  
41700  
41800  
41900  
42000  
42100  
42200  
42300  
42400  
42500  
42600  
42700  
42800  
42900  
43000  
43100  
43200  
43300  
43400  
43500  
43600  
43700  
43800  
43900  
44000  
44100  
44200  
44300  
44400  
44500  
44600  
44700  
44800  
44900  
45000  
45100  
45200  
45300  
45400  
45500  
45600  
45700  
45800  
45900  
46000  
46100  
46200  
46300  
46400  
46500  
46600  
46700  
46800  
46900  
47000  
47100  
47200  
47300  
47400  
47500  
47600  
47700  
47800  
47900  
48000  
48100  
48200  
48300  
48400  
48500  
48600  
48700  
48800  
48900  
49000  
49100  
49200  
49300  
49400  
49500  
49600  
49700  
49800  
49900  
50000  
50100  
50200  
50300  
50400  
50500  
50600  
50700  
50800  
50900  
51000  
51100  
51200  
51300  
51400  
51500  
51600  
51700  
51800  
51900  
52000  
52100  
52200  
52300  
52400  
52500  
52600  
52700  
52800  
52900  
53000  
53100  
53200  
53300  
53400  
53500  
53600  
53700  
53800  
53900  
54000  
54100  
54200  
54300  
54400  
54500  
54600  
54700  
54800  
54900  
55000  
55100  
55200  
55300  
55400  
55500  
55600  
55700  
55800  
55900  
56000  
56100  
56200  
56300  
56400  
56500  
56600  
56700  
56800  
56900  
57000  
57100  
57200  
57300  
57400  
57500  
57600  
57700  
57800  
57900  
58000  
58100  
58200  
58300  
58400  
58500  
58600  
58700  
58800  
58900  
59000  
59100  
59200  
59300  
59400  
59500  
59600  
59700  
59800  
59900  
60000  
60

NADC-80222-60

END  
DATE  
FILMED  
5 8  
DTIC

REPORT NO. NADC-80222-60

**LEVEL**

12



AD A 097813

**NAVAL AIR SYSTEMS COMMAND  
MAINTENANCE TECHNOLOGY PROGRAM  
SYSTEMATIC WEAR/CORROSION STUDY ANALYSIS OF ION PLATED SURFACES**

P. Agarwal, P. Nath, H. J. Doerr and R. F. Bunshah  
Department of Materials Science and Engineering  
University of California  
Los Angeles, California

and

G. Kuhlman, Materials Engineer  
Naval Engineering Support Office  
North Island Air Station, San Diego, California

FINAL REPORT

24 FEBRUARY 1981

CONTRACT N62269-79-C-0283

AIRTASK NO. 4114C0004

DTIC  
ELECTED  
APR 16 1981  
S C

*Approved for Public Release; Distribution Unlimited*

DTIC FILE COPY

Prepared for  
NAVAL AIR DEVELOPMENT CENTER  
Aircraft and Crew Systems Technology Directorate  
Warminster, Pennsylvania 18974

81 4 16 025

## NOTICES

**REPORT NUMBERING SYSTEM** - The numbering of technical project reports issued by the Naval Air Development Center is arranged for specific identification purposes. Each number consists of the Center acronym, the calendar year in which the number was assigned, the sequence number of the report within the specific calendar year, and the official 2-digit correspondence code of the Command Office or the Functional Directorate responsible for the report. For example: Report No. NADC-78015-20 indicates the fifteenth Center report for the year 1978, and prepared by the Systems Directorate. The numerical codes are as follows:

CODE	OFFICE OR DIRECTORATE
00	Commander, Naval Air Development Center
01	Technical Director, Naval Air Development Center
02	Comptroller
10	Directorate Command Projects
20	Systems Directorate
30	Sensors & Avionics Technology Directorate
40	Communication & Navigation Technology Directorate
50	Software Computer Directorate
60	Aircraft & Crew Systems Technology Directorate
70	Planning Assessment Resources
80	Engineering Support Group

**PRODUCT ENDORSEMENT** - The discussion or instructions concerning commercial products herein do not constitute an endorsement by the Government nor do they convey or imply the license or right to use such products.

APPROVED BY:



DATE: 24 February 1981

12

## AIRCRAFT MAINTENANCE TECHNOLOGY PROGRAM

PROGRAM ADMINISTRATOR

A. J. KOURY (AIR-4114C)  
Naval Air Systems Command

PROJECT LEADER

D. V. MINUTI (606B)  
Naval Air Development Center

PROJECT ENGINEER

R. F. BUNSHAH  
University of California, Los Angeles

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability/	
A	

NADC-80222-60

THIS PAGE INTENTIONALLY LEFT BLANK

Final rept.

6 Jul 79 - 31 Jul 80

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

19 REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NADC-80222-60	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE AND SUBTITLE SYSTEMATIC WEAR/CORROSION STUDY ANALYSIS OF ION PLATED SURFACES	5. TYPE OF REPORT & PERIOD COVERED FINAL REPORT 7/6/79 - 7/31/80	
6. AUTHOR(S) P. AGARWAL, P. NATH, H.J. DOERR, <del>AND</del> P.F. BUN- SHAH and G. KUHLMAN, NAVAL ENGINEERING SUPPORT OFFICE, NORTH ISLAND AIR STATION, S.D., CA.		7. PERFORMING ORGANIZATION NUMBER UCLA - ENC - 8043
8. PERFORMING ORGANIZATION NAME AND ADDRESS SCHOOL OF ENGINEERING AND APPLIED SCIENCE UNIVERSITY OF CALIFORNIA LOS ANGELES, CA. 90024		9. CONTRACT OR GRANT NUMBER(s) N-62269-79-C-0283
10. CONTROLLING OFFICE NAME AND ADDRESS NAVAL AIR SYSTEMS COMMAND (A.J.KOURY (AIR-4114C)) DEPARTMENT OF THE NAVY WASHINGTON, D.C. 20361		11. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
12. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) NAVAL AIR DEVELOPMENT CENTER WARMINSTER, PENNSYLVANIA 18974		13. REPORT DATE 24 Feb 1981
14. SECURITY CLASS. (of this report) UNCLASSIFIED		15. NUMBER OF PAGES
16. DISTRIBUTION STATEMENT (of this Report) APPROVED FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED.		17. SECURITY CLASS. (of this report) UNCLASSIFIED
18. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		19. DECLASSIFICATION/DOWNGRADING SCHEDULE
20. SUPPLEMENTARY NOTES		
21. KEY WORDS (Continue on reverse side if necessary and identify by block number) Activated Evaporation, Activated Reactive Evaporation, Chromium, Direct Eva- poration, Hafnium Nitride, Ion Plating, Localized corrosion, Nichrome, Overlay Coatings, Pitting, Titanium, Titanium Carbide, Titanium Nitride, Wear.		
22. ABSTRACT (Continue on reverse side if necessary and identify by block number) This study deals with the improvement in localized corrosion resistance and wear reduction of type M-50 steel used in engineering components such as bear- ings by use of overlay coating. Overlay coating materials selected for the improvement in localized corrosion (pitting) were titanium, chromium, nichrome (Ni-20Cr) and molybdenum deposited by physical vapor deposition techniques of direct evaporation (E), activated evaporation (AE), i.e. evaporation in the presence of a plasma, and ion plating (IP), and titanium carbide, titanium ni- tride and hafnium nitride coatings deposited by the activated reactive evapora-		

DD FORM 1 JAN 73 1473

EDITION OF 1 NOV 68 IS OBSOLETE  
S/N 0102 LF 014-6601

A

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

404637

U N C L A S S I F I E D

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

20, cont'd.

tion process (ARE).

Coated and control (uncoated) samples of M-50 steel were corrosion tested the test designed to simulate the bearing environment inside an engine, the roller bearing-on-race geometry, as specified by Memorandum DTNSRDC TM 28-77-117. The test samples were first immersed for two hours in a polyester oil (test fluid) contaminated with 3 ppm chlorine in the form of sea water at 85°C, drip-dried for 30 minutes and then placed in the holding fixture so that a meniscus of contaminated oil was retained between the two parts. This system was then exposed to alternate cycles of moist air at 60°C ± 1°C in an oven for 8 hours and 3°C ± 2°C environment in a refrigerator for 16 hours for a total period of two weeks. After the corrosion test, the samples were cleaned, the loose product wiped off, lightly polished and then examined under a microscope to observe the corrosion damage.

The results showed that the control (uncoated) samples were severely pitted along the contact line and general corrosion occurred outside this region, whereas the samples with overlay coatings of titanium, chromium, nichrome (Ni-20Cr), TiC, and TiN completely eliminated the localized pitting corrosion. Coatings of these materials deposited by different techniques showed equally good results. Overlay coatings of molybdenum showed corrosion presumably due to the reaction with the sulfur content of the polyester oil. Hafnium nitride coating also showed pitting in the areas where the coating had peeled off the substrate after deposition and prior to the corrosion test.

Wear test samples with TiC and other hard coatings were prepared and submitted to NESO, San Diego for Rolling Contact Rod Wear Tests.

U N C L A S S I F I E D

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

## TABLE OF CONTENTS

	<u>Page</u>
LIST OF TABLES. . . . .	ii
LIST OF FIGURES . . . . .	ii
OBJECTIVE . . . . .	1
IDENTIFICATION OF PROBLEM AREAS . . . . .	1
LOCALIZED CORROSION OF TYPE M-50 BEARING STEEL. . . . .	2
WEAR REDUCTION OF ENGINEERING COMPONENTS BY HARD OVERLAY COATINGS USING THE ROLLING CONTACT ROD WEAR TESTS . . . . .	20
WEAR REDUCTION BY HARD OVERLAY COATINGS UNDER OIL STARVATION CONDITIONS . . . . .	20
REFERENCES. . . . .	22
APPENDIX A. . . . .	A-1



## L I S T   O F   T A B L E S

<u>Table</u>	<u>Title</u>	<u>Page</u>
I	Summary of Localized Corrosion Test Results on M-50 Bearing Steel. . . . .	15

## L I S T   O F   F I G U R E S

<u>Figure</u>	<u>Title</u>	<u>Page</u>
1	Schematic of the Coating Apparatus. . . . .	5
2	Schematic of the Corrosion Test Arrangement . . . . .	6
3	Surface Photograph of an Uncoated and Uncorroded M-50 Steel Sample (Mag. X7) . . . . .	8
4	Unpolished Surface of Uncoated (control) and Coated Samples after Corrosion Test Run #1 (Mag. X4) . . . . .	9
5	Unpolished Surface of Uncoated (control) and Coated Samples after Corrosion Test Run #2 (Mag. X4) . . . . .	10
6	Polished Surface of Uncoated (control) and Coated Samples after Corrosion Test Run #1 (Mag. X4) . . . . .	12
7	Polished Surface of Uncoated (control) and Coated Samples after Corrosion Test Run #2 (Mag. X4) . . . . .	13
8	Polished Surface of Uncoated and Coated Samples after Corrosion Test Run #1 . . . . .	16
9	Polished Surface of Uncoated and Coated Samples after Corrosion Test Run #2 . . . . .	17

## I. OBJECTIVE

This contract calls for a review of critical aircraft wear components, selection of some of these components for potential wear reduction by ion plating/ion implantation and similar processes in cooperation with NESO personnel, application of the selected surface treatments and testing of the coated components.

## II. IDENTIFICATION OF PROBLEM AREAS

As requested by the program sponsor, Mr. A. J. Koury of NAVAIR, Professor R.F. Bunshah visited NARF facilities at North Island, San Diego, on August 17, 1979, and met with David Stanley, Gary Kuhlman, Jeff Sakai and Phil Borja of the Materials Engineering Laboratory, Building 341, Code 340. A second visit was also made some weeks later. From these discussions, three projects were identified for investigation under this contract.

1. Localized Corrosion of type M-50 steel used in subcomponents such as bearings.

This is a serious problem costing in excess of \$1 million for replacement of turbojet bearings alone. NRL is currently evaluating ion implantation to improve the pitting corrosion of AISI M-50 bearing alloy used in Navy turbojet engines. The worst corrosion problems occur in engines which experience intermediate usage and is exhibited by localized pitting at contact points between the bearing race and the rollers after engine shutdown. Ion implantation of corrosion resistant elements such as Cr at NRL shows that corrosion is significantly reduced in simulated field service corrosion tests with a salt-water contaminated polyester lubricant.<sup>(1)</sup>

Since ion implantation is a slow and costly process, it was decided that potentially faster and cheaper overlay coating techniques to improve corrosion

resistance would be investigated.

2. Wear Reduction of Engineering Components by Hard Overlay Coatings Using Rolling Contact Rod Wear Tests.

AISI M-50 steel rods were to be overlay coated with various hard compounds such as TiC, TiN,  $Ti_2N + TiN$ , etc., and tested by NADC in a Rolling Contact Fatigue Test machine.

3. Wear Reduction by Hard Overlay Coatings Under Oil Starvation Conditions

TiC or other hard coatings were to be deposited onto wear test blocks of CBS 600 material (Timken Company proprietary alloy) to be tested in a Timken Wear Test Device.

### III. LOCALIZED CORROSION OF TYPE M-50 BEARING STEEL

#### A. Experimental Program

1. Selection of Coating Materials and Coating Techniques:

A number of coating materials which are known to have good corrosion resistance were selected for the present study to improve the localized corrosion resistance of M-50 bearing steel. The coating materials are titanium, molybdenum, chromium, nichrome (Ni-20Cr), titanium carbide, titanium nitride and hafnium nitride. These coatings were deposited in a vacuum chamber using an electron-beam heated evaporation source.

Several Physical Vapor Deposition techniques used to deposit single metal or alloy coatings were: (i) Direct Evaporation (E), (ii) Activated Evaporation (AE), i.e. evaporation in the presence of a plasma, and (iii) Ion Plating (IP). The compounds titanium carbide and titanium nitride were deposited by the Activated Reactive Evaporation Process (ARE). These processes are briefly defined below:

- (i) Direct Evaporation: Direct evaporation is a process in which vapors

are produced from a liquid (or solid) source in vacuum where there is almost no surrounding gas. The escaping vapor atoms will travel in a straight line for some considerable distance before they collide with something; for example, the vacuum chamber walls, the substrate, or other vapor atoms. It is a line of sight process. The substrate is not biased and is usually at ground potential.

(ii) Activated Evaporation: This is a variation of direct evaporation carried out in the presence of a plasma; i.e. the vapor phase contains neutral atoms, energetic neutral atoms, positive ions and free electrons. The substrate is usually not biased and is at ground potential.

(iii) Ion Plating: Ion plating is a variation of the evaporation process in which the substrate is biased to a high negative potential which sets up a plasma due to an inert gas partial pressure (usually 10 to 50  $\mu\text{m}$ ) introduced into the chamber. Initially, the substrate and subsequently, the growing fiber is bombarded by the positive ions of the inert gas. A very small fraction of the evaporated metal flux is also ionized. The ion bombardment causes heating and microstructural rearrangements to occur in the deposited coating.

(iv) Activated Reactive Evaporation (ARE) Process: Activated Reactive Evaporation is a process for the deposition of refractory compounds by reaction between metal vapor atoms and molecules of a reactive gas (such as  $\text{C}_2\text{H}_2$  or  $\text{N}_2$  for the deposition of carbides or nitrides respectively). The reaction is aided by the presence of a plasma in the reaction zone (i.e. between the evaporation source and the substrate). The plasma is created by extracting the low energy secondary electrons from the plasma sheath above the molten pool by an electric field created by biasing an electrode placed above the molten pool to a small positive potential of 20 to 100 volts DC (or AC).

## 2. Materials Preparation and Coating Methodology

Rods of M-50 steel, 3/8" in diameter were supplied by Gary Kuhlman of NARF. Test samples of M-50 steel, 3/8" in diameter and 3/8" in height were cut from these rods. The faces of these cylindrical test samples to be coated and corrosion tested were polished using conventional surface preparation methods with the final alumina particle size being 0.05  $\mu\text{m}$ . Duplicate samples were used for each coating material and each coating technique.

Figure 1 shows a schematic of the apparatus used for coating. To make a coating experiment, the samples were thoroughly cleaned, degreased and then mounted in a specially prepared substrate holder located just below the substrate heater. A base pressure of  $10^{-5}$  torr or better was attained in the vacuum chamber and the samples were heated to approximately 350°C for 1/2 hour before evaporation and deposition of the coating material. Evaporation was accomplished by using an electron beam heated source, and the coating thickness was 5-7  $\mu\text{m}$ . Samples were slowly cooled to room temperature before opening the vacuum chamber. Samples were examined for coating integrity and then used for corrosion testing.

## 3. Corrosion Simulation Test

Corrosion tests on the coated and control (uncoated) samples of M-50 steel were carried out following the procedure described in memorandum DTNSRDC TM 28-77-117. A copy is attached as Appendix I. This test is designed to simulate the bearing environment inside an engine. Figure 2 shows the arrangement of the test set-up. The cylindrical surface resting on the flat side of the upright cylinder is intended to simulate the roller bearing-on-race geometry. The cylinders were positioned in place and totally immersed for two hours in a polyester oil contaminated with 3 ppm chloride in the form of sea water. The two parts were then removed from the oil and allowed to drip dry for 30





Figure 1: Schematic of the coating apparatus

1. Test pieces (both M50 alloy steel) were placed in contact as indicated by the dotted line.



2. Both pieces in place were immersed in chloride-contaminated oil for 2 hrs., removed, and allowed to dry.
3. A meniscus of contaminated oil was retained between the two parts:




Figure 2 : Schematic of the corrosion test arrangement


minutes before being placed in the holding fixture. A meniscus of contaminated oil was retained between the two parts, as shown in Figure 2. This system was then exposed to alternate cycles of moist air at  $60^{\circ}\text{C} \pm 1^{\circ}\text{C}$  in an oven for 8 hours and a  $3^{\circ}\text{C} \pm 2^{\circ}\text{C}$  environment in a refrigerator for 16 hours for a total period of two weeks. After the corrosion test, the samples were cleaned with benzene and acetone, and the loose corrosion product was wiped off the surface. The surface was then examined under a microscope.

#### B. Results and Discussion

Two separate corrosion test runs were carried out. The first corrosion test (11 samples) included the following samples: two control samples (uncoated), one sample each coated with titanium, molybdenum and nichrome with each coating material deposited by direct evaporation (E), activated evaporation (AE) and ion plating (IP). The results of this test were reported in Progress Report Number 1, dated April 17, 1980. It is believed that the polyester oil contaminated with chlorine (sea water) contained a somewhat higher level of chlorine than the recommended 3 ppm in the test procedure. This problem was corrected in the second corrosion test run (12 samples) which included the following samples: two control samples (uncoated), one sample each coated with TiC, TiN and HfN, two samples coated with chromium deposited by direct evaporation and activated evaporation, and duplicate samples coated with titanium, molybdenum and nichrome. Results of each corrosion test are presented separately in the form of photograph micrographs at 4x magnification of scattered light from the flat surfaces.

Figure 3 shows polished surface of a virgin (uncoated and uncorroded) sample. Figures 4 and 5 show the surfaces of control (uncoated) and coated samples after corrosion test runs 1 and 2, respectively. No polishing has been done on these samples after corrosion testing and therefore corrosion products are clearly





**Figure 3 : Surface photograph of an uncoated and uncorroded M80 steel sample (Mag. X7)**




Figure 4 : Unpolished surface of uncoated (control) and coated samples after corrosion test run #1. (Mag. X4).

E: Evaporation, AE: Activated Evaporation, IP: Ion Plating, ARE: Activated Reactive Evaporation.



CR-E



Mo-E



NiCr-AE



HfN-AE



Cr-AE



TiN-AE



Ti-IP



Ti-AE



TiC-AE



Uncoated



Uncoated

Figure 5 : Unpolished surface of uncoated (control) and coated samples after corrosion test run #2.(Mag. X4)

visible. All samples show a contact line on the surface which had developed from the cylindrical surface of the top sample during the corrosion test. Uncoated samples were completely covered with a "black" corrosion product and also showed a few deep pits on the surface. Most of the coated samples were partially covered with a corrosion product along both sides of the contact line, but no pits were observed on these surfaces. Titanium, chromium, nichrome and titanium carbide coatings by all the deposition techniques used in this investigation, were well-adherent and continuous on all samples, whereas ion plated molybdenum and hafnium nitride coatings had partially come off the surface and showed pits in the exposed areas. There was some damage observed at the edges of other molybdenum coatings and titanium nitride coating.

To observe the actual corroded surface, it was necessary to remove the corrosion product from all the samples. Therefore, the samples were lightly polished with 0.05  $\mu\text{m}$ .  $\text{Al}_2\text{O}_3$  grit in a slurry until only a few traces of corrosion product were left on the surfaces which ensures that the coating is not polished off the surface. Figures 6 and 7 show the polished surfaces of control (uncoated) and coated samples after corrosion test runs 1 and 2, respectively. The effect of corrosion can clearly be seen in these figures. For corrosion test run number 1, the control sample shows severely pitted and damaged area along the contact line. The attack generally occurs in two areas, e.g., a line of pits beneath the contact line between the cylindrical and flat surfaces, and general corrosion in the thin layer of oil outside this region. For corrosion test run 1, the uncoated sample shows severe corrosion whereas with the exception of one coated sample, none of the coated samples show any type of pitting or any other type of corrosion damage to the surface. The exception is the ion plated molybdenum sample where the coating had partially




Figure 6 : Polished surface of uncoted (control) and coted samples after corrosion test run #1.(Mag. X4)



Figure 7 : Polished surface of uncoated (control) and coated samples after corrosion test run #2.(Mag. X4)

come off the surface. However, there is no pitting on the coating itself, but only in the exposed regions of the M-50 steel. This indicates that although molybdenum is resistant to corrosion, the coating either is not well-adherent to M-50 steel or is attacked by the lubricant fluid containing some sulfur compounds which presumably may react with the Mo coating. Titanium and nichrome coatings deposited by all three techniques do not show any type of pitting or any other type of damage. A contact line is observed on the soft nichrome coated sample (by direct evaporation) which is believed to be deformation markings from the cylindrical surface of the sample lying on top.

Figure 7 shows the polished surfaces of samples from corrosion test run 2. Again, the uncoated sample shows severe pitting along the contact line, and general corrosion on the rest of the surface. The damage is, however, not as severe as for the uncoated sample from corrosion test run 1. The reason for this is the higher amount of chloride (more than the recommended 3 ppm) in the test fluid for the corrosion test run 1. Samples coated with chromium, titanium, nichrome and titanium carbide show no corrosion damage. Titanium nitride coating also shows no corrosion, but has come off at the edges. The hafnium nitride coating has come off the surface at many areas and shows pitting in those regions. The hafnium nitride coating itself appears rough and very thick. It is not clear whether the hafnium nitride coating came off the surface due to its higher thickness or whether it is the corrosion attack. The coating performance results for corrosion test runs 1 and 2 are summarized in Table 1.

Figures 8 and 9 show the photographs of selected samples from the corrosion tests 1 and 2, at a magnification of seven times. These photographs clearly show the severe corrosion damage on uncoated samples whereas no pitting or any other type of corrosion damage on titanium, nichrome, chromium, titanium carbide and

Table 1: Summary of Localized Corrosion Test Results on M-50 Bearing Steel

<u>Coating</u>	<u>Process</u>	<u>Corrosion Test Results</u>
<u>Corrosion Test #1</u>		
Uncoated	-	Severe pitting corrosion along the contact line and general corrosion on rest of the surface.
Titanium	E	No corrosion.
Titanium	AE	No corrosion.
Titanium	IP	No corrosion.
Molybdenum	E	Coating damaged at edges but no pitting in coated area.
Mo	AE	Coating damaged at edges but no pitting in coated area.
Mo	IP	Coating peeled off. Sample corroded.
Nichrome	E	No corrosion but marking along the contact line due to deformation of the soft coating.
Nichrome	AE	No corrosion.
Nichrome	IP	No corrosion but marking along the contact line due to deformation of the coating.
<u>Corrosion Test #2</u>		
Uncoated	-	Pitting corrosion along the contact line and general corrosion on rest of the surface.
TiC	ARE	No corrosion.
TiN	ARE	No corrosion but slight damage at edges.
HfN	ARE	Corrosion attack in the areas where coating had come off, possibly due to the greater thickness.
Cr	E	No corrosion.
Cr	AE	No corrosion.
Ti	AE	No corrosion.
Ti	IP	No corrosion.
Ni-Cr	AE	No corrosion.
Mo-E		Coating damaged at edges.

E: Direct Evaporation  
 AE: Activated Evaporation  
 IP: Ion Plating  
 ARE: Activated Reactive Evaporation






Figure 8 : Polished surface of uncoated and coated samples after corrosion test run #1.

All coated samples show no pitting. (Mag. X7)






Figure 9 : Polished surface of uncoated and coated samples after corrosion test run #2.

All coated samples show no pitting.(Mag. X7)



TI-AE



TI-IP

Figure 9 : continued

titanium nitride coated samples was observed.

### C. Summary and Conclusions

Seven different overlay coatings were deposited onto flat surfaces of type M-50 bearing steel and subjected to a standard localized corrosion test as prescribed in Memorandum DTNSRDC TM 28-77-117 (Appendix I).

The results show that overlay coatings of titanium, nichrome (Ni-20Cr), chromium, TiC, and TiN completely eliminate the localized pitting corrosion of Type M-50 bearing steel in an environment of engine lubricant containing chloride ions. The coatings were deposited by three different physical vapor deposition techniques. Overlay coatings of molybdenum showed corrosion presumably due to the reaction with the sulphur content of the lubricant. Hafnium nitride coating also showed pitting in the areas where the coating had peeled from the substrate after deposition and prior to the corrosion test.

These data show that coatings of Ni-20Cr, Ti, Cr, TiC and TiN inhibit localized corrosion in the selected environment and test conditions equal to the results obtained by ion implantation of Cr.<sup>(2)</sup>

Since the TiN and TiC hard overlay coatings reduce wear as well as improve corrosion resistance, this represents a promising new development over ion implanted materials from two viewpoints. One, overlay coatings are effective in reducing wear even in dry (i.e. unlubricated) or starvation lubrication conditions, whereas ion implantation is not effective under these conditions.<sup>(3)</sup> Second, overlay coating processes are currently much less expensive than ion implantation.

A further point to be considered is as follows. As stated by Hirvonen and Butler<sup>(1)</sup>, it is generally believed that coatings reduce the fatigue life of components whereas ion implantation does not. This now has been shown to be incorrect since ion-implanted noble metal coatings and overlay hard coatings

(ref. T. Spalvins NASA-Lewis)<sup>(4)</sup> increase fatigue life. The important factor to be considered is whether the surface treatment (i.e. overlay coating, diffusion coating or ion implantation) produces tensile or compressive residual stresses on the surface. If they are tensile stresses, the fatigue life will decrease and if they are compressive the fatigue life will increase. A proper choice of coating parameters can give compressive stresses. Hence this problem should be recognized and used to advantage. The case can therefore be made for further studies on corrosion resistance and fatigue behavior of components using cheaper overlay coatings as compared to the more expensive ion implantation process.

#### IV. WEAR REDUCTION OF ENGINEERING COMPONENTS BY HARD OVERLAY COATINGS USING THE ROLLING CONTACT ROD WEAR TESTS

Four rods of Type M-50 high speed steel 6 inches long were coated on the cylindrical surface for a length of 3 inches. The coatings were deposited using the ARE process. The coating composition and thicknesses are:

	<u>Composition</u>	<u>Thickness</u>
1.	TiC	5-6 $\mu$ m.
2.	TiC/Ti/TiC (multiple layers)	5-6 $\mu$ m.
3.	TiC	1-2 $\mu$ m.
4.	TiN	5-6 $\mu$ m.

The coated rods have been forwarded to Mr. Gary Kuhlman, NARF, NAS, North Island, San Diego, for testing.

#### V. WEAR REDUCTION BY HARD OVERLAY COATINGS UNDER OIL STARVATION CONDITIONS

TiC coatings 4-5  $\mu$ m. thickness were deposited onto two test blocks of case carburized CBS 600 steel on two adjacent surfaces at a deposition temperature of 180°C using the ARE process. They were tested by the Timken Company with the Timken Lubricant and Wear Test Machine using an oil-off scoring resistance

procedure. The results showed no improvement for the coated versus the untreated surface<sup>(5)</sup>. The report from Timken indicated that the coating deposited at 180°C was non-uniform in comparison to a previous coating where the deposition temperature was 540°C. It is difficult to draw many conclusions from a single test run. Obviously, if a lower deposition temperature is necessitated by the substrate material tempering parameters, the coating parameters and thicknesses must be varied. While this single test yielded poor results, other data on improvements in friction and wear using hard overlay coatings<sup>(3,4,6)</sup> justifies a more detailed study in the future.

References

1. J.K. Hirvonen and J.W. Butler, "Improved Corrosion and Mechanical Behavior of Alloys by Ion Implantation," presented at joint AF/Navy Science and Engineering Symposium, San Diego, California, October 17-19, 1978.
2. G. Hubler, et al, "Application of Ion Implantation for Improvement of Localized Corrosion Resistance of M-50 Bearing Steels," NRL Report to be published.
3. A.K. Suri, R. Nimmagadda and R.F. Bunshah, "Application of Ion Implantation and Ion Plating on Stainless Steel, Titanium and Aluminum," U.C.L.A., December 1978. Report No. NADC-79128-60. Also published in Thin Solid Films, Vol. 64, Page 191 (1979).
4. T. Spalvins, "Industrial Potential, Uses and Performance of Sputtered and Ion Plated Films," Metal Finishing, January 1980, Page 17.
5. P.S. Orvos, "Wear Tests of Overlay Coated (TiC) CBS 600 Steel," The Timken Company Physical Laboratory Report, Test No. 281.3.0, Supplement 1, May 1980.
6. T. Jamal, R. Nimmagadda, and R.F. Bunshah, "Friction and Adhesive Wear of Titanium Carbide and Titanium Nitride Overlay Coatings," presented at the International Conference on Metallurgical Coatings, April 21-25, San Diego, California. To be published in Thin Solid Films, 1980.

NADC-80222-60

A P P E N D I X    A

CORROSION EXPERIMENT METHOD

DTNSRDC TM 28-77-117




## Corrosion Experiment Method

Each experiment is started on a Monday morning. The corrosion cell is a one litre glass bottle with a rubber stopper covered with polyvinyl plastic film. A 100 ml portion of distilled water is added to each cell. The bearing to be used is cleaned with successive washings in two baths each of benzene, naphtha, and acetone, in that order. It is air dried, then immersed in the fluid under evaluation at 83°C, with hand rotation every ten minutes for a two-hour soak period. Prior to use, 3 p/m of chlorides are added to the fluid under evaluation as ASTM D-665 seawater; then the water content of the fluid is adjusted to 600 p/m total water by addition of distilled water. The bearing is then drained 30 minutes at ambient temperature and then suspended, using a corrosion resistant wire, from the rubber stopper over the water in the cell. The bottle is closed and the cell placed in an oven for the start of a 14-day exposure period. During this period the cell is temperature cycled every 24 hours in a 60°C  $\pm$  1°C oven for 8 hours and in a 3°C  $\pm$  2°C refrigerator for 16 hours. The cells remain in the oven during each of two weekends, with the oven heater shut off at 1600 on Friday and turned on the 0800 on Monday. After the initial 24 hours of the exposure period, the distilled water is replaced with a fresh amount of distilled water. After the 14-day exposure period, the bearings are disassembled. The races and balls are prepared for inspection by cleaning with benzene and acetone and loose products of corrosion are wiped off of bearing surfaces. The number of pits of 0.01" diameter, or larger, are counted at 15 x magnification.

DTNSRDC TM 28-77-117

CORROSION TEST CELL



1 LITER CELL

NAPTC-WUA-782

## D I S T R I B U T I O N   L I S T

	<u>No. of Copies</u>
NAVAIRSYSCOM (AIR-950D) . . . . .	5
2 for retention	
1 for AIR-4114C	
1 for AIR-5163	
1 for AIR 320	
NAVMAT (Code 08EB) . . . . .	1
ONR (Code 211) . . . . .	1
NRL (Code 6170) . . . . .	1
COMNAVAIRLANT (Code 528) . . . . .	1
COMNAVAIRPAC (Code 74) . . . . .	1
NAVAIREWORKFAC, NAS, Alameda (Code 300 & 340) . . . . .	2
Jacksonville (Code 300 & 340) . . . . .	2
North Island (Code 300 & 340) . . . . .	2
Norfolk (Code 300 & 340) . . . . .	2
Pensacola (Code 300 & 340) . . . . .	2
MCAS, Cherry Point (Code 300 & 340) . . . . .	2
COM NAR (Code 32) . . . . .	1
CNATRA . . . . .	1
NAVAIRENGCEN (ESSD ES-1) . . . . .	1
NAVAIRTESTCEN . . . . .	1
NAVMIRO (Code 224) . . . . .	1
CMC (Code AA J5) . . . . .	1
San Antonio Air Materiel Area (MMEW) . . . . .	1
Kelly Air Force Base, TX 78241	
Air Force Materials Laboratory (AFML/LTM) . . . . .	1
Wright Patterson AFB, OH 45433	
Sacramento Air Logistics Center (MAGC) . . . . .	1
McClellan AFB, Sacramento CA 95652	
Warner-Robins Air Materiel Area (MME) . . . . .	1
Robins AFB, GA 31094	
U. S. Army Aviation Systems Command (CCAD/SAVAE-GG) . . . . .	1
Corpus Christi, TX 78419	
U. S. Army Materials & Mechanics Research Center . . . . .	1
Watertown, MA 02172	
U. S. Army Air Mobility Research & Development Lab . . . . .	1
AMES Research Center, Moffett Field, CA 94035	
DTIC . . . . .	12

DATE  
FILMED  
— 8